

PRODUCT UPDATE



Hub Seal Changed: SL10 Model

LIT NO: W&C243

REVISION: A

DATE: 05/21/19

New: Gold 38 Series Seal - M380047TX:

Description Change

Hub seal 370047A is being obsoleted by Federal Mogul in this application, and production was changed to the improved M380047TX Gold 38 Series seal.

Parts Affected

Two (2) hub seals per suspension.

Model Affected

Watson & Chalin SL10 series

Dates Affected

Units built after September 2018.

Installation Method

Hub-type installation has not changed.

Parts Availability

The new seals are in stock at Watson & Chalin. You may use up your current stock, but please note that the newer version should increase seal life.

The **Gold 38 Series** is made with an exclusive PTFE compound that withstands extreme temperatures and includes a unique exclusion design to help keep contaminants out.



Seal used before October 1, 2018
WC# 370047A
National Red Seal



Seal after October 1, 2018
WC# M380047TX
Gold 38 Series

*Actual product performance may vary depending upon vehicle configuration, operation, service and other factors.
All applications must comply with applicable specifications from Watson & Chalin and the respective vehicle manufacturer.
Contact Watson & Chalin for additional details regarding specifications, applications, capacities, and operation, service and maintenance instructions.*

Contact Watson & Chalin at 972.547.6020 for additional information.



Watson & Chalin

725 E. University Drive, McKinney, Texas 75069
972.547.6020 • 800.445.0736 • Fax 972.542.0097

www.watsonsuspensions.com

